	er ID 76493 ber 15, 2011 3:58:12 P	PM		*764	193*						Page 1
Revision ID:	D3324-041 Basket Base Assembly			Accept	*N900)()4()	100) * s	Setup Sta	171	S1* S2*
	11/15/2011 Start Qt	-	*1* *1*		Cust Item Customer:						
Approvals:	Process Plan:	6	Date://-/	Tooling: SPC (Y/N):		Date:		J	Run Sta Sto	" [\] on	R1* R2*
Sequence ID/ Work Center II	Operation Description			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr										
D3324	Rev B									, i	
*100 *100* Large Fab Large Fab	Large Fab	Otty Part 3 D3 4 D3 2 D3 10 D3 2- Weld as p	324-5 Top End T 324-7 Bottom E 324-9 Vertical T	be 109137 n Tube 109137 ube 109137 ndTube 109127 Tube 109137] [](:e(*·54	lx	9	· 	
110 *110* QC Quality Control	QC9- Inspe	ect visual per	QSI004- Fusion Welds	0.00	M	Med	1.2	1	·		

Dart	Aeros	space	Ltd
------	-------	-------	-----

W/O:			W	ES			1	
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date 0	Approva Chief Eng Prod Mgr	Approvai
		Park and William a					Prod Mgr	<u>'</u>
Part No		PAR #:	Fault Cat	tegory:	NCR: Yes	No DQA:	Date:	
	Resolution:			ion:	_ QA: N/C CI	osed:	Date:	
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NCF	R)		
DATE	CTED	Description of NC		Corrective Action Section		Verificati	ion Approva	I Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section (QC Inspector
						:		

Work Ord Tuesday, Novem				*764	193*							Page 2
Item ID: Revision ID: Item Name:	D3324-041 Basket Base A			Accept	*N900	040	100)*	Setup	Start Stop	ı V.	S1* S2*
Start Date: Required Date:	11/15/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:						
Reference: Approvals:	Process Pla	nn:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop	1711	R1* R2*
Sequence ID/ Work Center I		Operation Description	atomasa ta atom an W/O	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
*120 *120* QC Quality Control		QC5- Inspect part compl	eteness to step on w/O		luizt							
121		Pressure Wash per QSI0	05 4.3	0.00				/\/ .		1. <i>1</i>	/	/ / .
121 HandFinish Hand Finishing		Memo		0.00			V	X]	V//	A A.	/11/25

Hand Finishing

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
-														
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQA: _	Date: _							
	R	esolution:	Disposition	on:	QA: N/C CI	osed:	Date: _							
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)								
		Description of NC		Corrective Action Section		Verification	n Approval	Approval						
DATE	STEP	Section A	initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector						
		:												

Work Orde Tuesday, Novem				*764	.93*					F	Page 3
Item ID: Revision ID:	D3324-041	Accombile		Accept	*N900	040	100°	k Setup	Start Stop	*NS1	*)*
Item Name: Start Date: Required Date:	Basket Base / 11/15/2011 11/25/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	ID:				14.72	
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):		ate:		Run	Start Stop	*NR1	*)*
Sequence ID/ Work Center II 130 *130* Powdercoat Powder Coating		FINISH TIN ******** 2ND COAT START TIN	AE:APERATURE:AE:	Set Up/ Run Hours 0.00 0.00 100 100 100 100 100 10	Tool ID	Tool#		Accept Re Qty Qt	-	Reject Insp Number Stan	
*140 *140* QC		QC3- Inspect Part Finish	1	0.00			_	[[X	, <u>/1-</u> [/	- <u> 28.</u>	

Quality Control

W/O:			W	ORK ORDER CHANG	ES			*
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							Frod Wigi	
Part No		PAR #:	Fault Cat	egory:	NCR: Yes	No DQA:	Date: _	
		esolution:						
NCR:			WORK ORE	DER NON-CONFORMA	NCE (NCR)			
DATE	OTED	Description of NC		Corrective Action Section		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector

	ler ID 764 mber 15, 2011			*764	193*				Page 4
tem ID: Revision ID:	D3324-041			Accept	*N900040	100*	Setup S	Start Stop	*NS1* *NS2*
tem Name: Start Date: Required Date	Basket Base As 11/15/2011 e: 11/25/2011	sembly Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:				INO
Reference: Approvals:	Process Plan	l:	Date:	Tooling:	Date:			Start Stop	*NR1* *NR2*
Sequence ID/ Work Center 1	ID .	Operation Description Identify as per dwg & Sto	ock Location: 6-A	Set Up/ Run Hours 0.00	Tool ID Tool #	Plan Accep Code Qty	t Reject Oty		teject Insp. fumber Stamp
150 Packaging Packaging		Memo	46489 ,	0.00					
ւ *160	·	QC21- Final Inspection -	Work Order Release	0.00				11	111/29 1
OC		Memo		0.00					

Memo

Quality Control

W/O:			W	ORK ORDER CHANG	ES			*	
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									٠.
<u> </u>				3.00	<u> </u>				
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQA	\:	Date:	
	R	esolution:	Dispositi	on:	_ QA: N/C CI	osed:		Date: _	
NCR:		V	VORK ORE	DER NON-CONFORMA	NCE (NCF	R)		e.	
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
					;				
				1.0					

Picklist Print

Tuesday, November 15, 2011 3:58:17 PM

Work Order ID: 76493

76493

D3324-041

Parent Item:

Parent Item Name:

D3324-041

Basket Base Assembly

Start Date: 11/15/2011

Start Qty: 1.00

Required Date: 11/25/2011

Page 1

Required Qty: 1.00

Comments:

IPP Rev:A05.02.09New issueKJ/JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Status Issued
D3328-3		Manufactured	No			100	Each	18.0000	2	2 /. /	,	1
D3328-3 Basket Hinge									**	SY	11/11	121
-				Location	ļ.	<u>Loc</u>	Oty	Loc Code				
				WA005			18		-/			
					33872		18		Ę	(dx)		
D3348-1		Manufactured	No			100	Each	15.0000	4	4	/ /	1
D3348-1									**	S	1///	101
Clevis				Location	<u>.</u>	Loc	<u>Oty</u>	Loc Code				
				WA			14					
					75575		14			(4x)		
				WA005			1					
					44246		1		_			
D3349-3		Manufactured	No			100	Each	4.0000	2	2 /	1 1	' / .
D3349-3 Spacer Bushing									**	<i>S</i> .	1 1/1	11/2/
op				Location	<u>l</u>	Loc	<u>Oty</u>	Loc Code				
				WA			4		_			•
					72930		4			(8x)		
D3367-1		Manufactured	No			100	Each	8.0000	2	~ /	. /	1 /
D3367-1 Mounting Bracket	·								**	-D	7 11/	11/21
Trouming District				Location	<u>Į</u>	Loc	<u>Oty</u>	Loc Code				
				WA005			8		_			
					43228		8			12x		

W/O:			W	ORK ORDER CHANG	ES		•		
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								Frod Wigi	
	:								
							<u> </u>		
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
		Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	tion C	Chief Eng	QC Inspector
							····		
	,								
							,		

Picklist Print									Page 2
Tuesday, November 15, 2011 3:	58:17 PM								<u> </u>
Work Order ID: 76493		*7	6493*						
Parent Item: D3324-041			3324-041*						
Parent Item Name: Basket Base	Assembly	• .	,,,,,,, ,, ,,,,,,,,,,,,,,,,,,,,,,,,,,			Star	t Date: 11	1/15/2011	Required Date: 11/25/2011
						Sta	rt Qty: 1.	00	Required Qty: 1.00
M4130NTS0.500W.035	Purchased	No		100	f	307.3682	46.6	49.0526	53
*M4130NTS0 5						t	**		Gl 11.11.24
•			Location	<u>L</u>	oc Oty	Loc Code			
			MAT034	30	7.3682			- 10 0	Z 01 0
			109127		58.152			49.0	5963
			109385		15.75				_
			112786		9.2488				_ ·
			119441	:	36.34				
M569EX0.50-18F	Purchased	No	119506	100	30.34 sf	146.0000	28	28 ,	_
*M569FX0 50-						7	* *	SM	11/1/21
569 Expanded Metal	IOE								11110
309 Expanded Metal			Location	<u>L</u>	oc Qty	Loc Code		,	$\frac{d}{dt}$
			MAT018		146				_
			112776		10				_
			117806		4				

128

119226


W/O:			W	ORK ORDER CHANG	GES						
DATE STEP		PR	OCEDURE CHA	NGE	Ву	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
					-						
Part No	s	PAR #:	Fault Cate	gory:	NCR: Yes	No D	QA:	Date: _			
Resolution:		esolution:	Dispositio	n:	QA: N/C Closed: Da			Date: _	_ Date:		
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)					
DATE	OTED	Description of NC	C Corrective Action Sec			Veri	fication	Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Se	Section C	Chief Eng	QC Inspector		
					-						
					:			- - -			
								-	:		
								:			



DESIGI		ORAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECK	(ED)	APPROVED	DRAWING NO. REV. B
	9	#	D3324 SHEET 1 OF 3
DATE			TITLE SCALE
05.0	3.04		BASKET BASE ASSEMBLY NTS
Α		04.10.20	NEW ISSUE
В		05.03.04	UPDATE MESH MATERIAL SPEC

PARTS LIST FOR D3324-041 BASKET BASE ASSEMBLY

Part No.	Quantity (-041)	Length A	Length B	Length C	Description
D3324-1	3	14.00	N/A	N/A	BOTTOM TUBE
D3324-3	4	N/A	86.50	N/A	FULL LENGTH TUBE
D3324-5	2	N/A	16.00	N/A	TOP END TUBE
D3324-7	2	N/A	15.00	N/A	BOTTOM END TUBE
D3324-9	10	N/A	N/A	11.04	VERTICAL TUBE
D3328-3	2	N/A	N/A	N/A	HINGE PLATE
D3348-1	4	N/A	N/A	N/A	CLEVIS
D3349-3	2	N/A	N/A	N/A	SPACER BUSHING
D3367-1	2	N/A	N/A	N/A	MOUNTING BRACKET




D3324-1/-3/-5/-7/-9

- 1) CUT LENGTH/SHAPE PER DIAGRAM AND PARTS LIST
- 2) MATERIAL: 4130 COND. N SQ. TUBE PER MIL-T-6736, 1/2" SQ. x 0.035 WALL (REF. DART SPEC M4130N-TS0.500W.035)
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2005 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES									
DATE STEP		. PROCEDURE CHANGE			Ву		Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQA:	Date: _				
		esolution:	Disposition	Disposition:		osed:	Date: _				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	R) : .	•				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sect Action Description Chief Eng	ion B Sign & Date	Verification (Approval QC Inspector			
	* 1										



bart horuspen.	1 1							
AA\c)		/**	• 25 €" - 1 × 1 ·	PER CHANGE	S			•
. UPIE (SIEM)	766 - 1874 - 187				Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,,		
Part No.	*F. + +	rault Gab	TS (8 9)		NCR: Yes	No DQA :	Date: _	
	Siction	Hispositi				osed:		
rich.		WGHL ORL	ar et kiet (CONFORMAN	ICE (NCR)		
	οσούημαν το Ευδ		Consectiv	e Action Section	В	Verification	Approvai	Approval
DRIE SIEM	www.	fittial and a Cog	m (-Éi	on Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	,							
NOTE: Date 3. initia	i a condite o	(1					1	

DESIGN PH	PH	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
CHECKED	APPROVED	DRAWING NO.	REV. B
THE		D3324	SHEET 3 OF 3
DATE		TITLE	SCALE
05.03.04		BASKET BASE ASSEMBLY	1:8




Copyright © 2005 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES									
DATE STEP		PRO	CEDURE CH	ANGE	By Date Qty Chief Eng Prod Mgi						
7,7											
Part No	•	PAR #:	Fault Cat	tegory:	_ NCR: Yes 1	No DQA:		Date:			
	R	esolution:	Dispositi	on:	_ QA: N/C Clo	Date:					
NCR:		1	VORK ORI	DER NON-CONFORMA	NCE (NCR)						
DATE	STEP	Description of NC		Corrective Action Section Action Description		Verification		Approval	Approval		
DAIL	SIEF	Section A	Section A Initial Chief Eng		Sign & Date			Chief Eng	QC Inspector		
		·									

^{*} H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



Dart Aerospace L	∟td	
------------------	-----	--

W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						Mafe	4.5					
					***	3	, i					
					\$	<i>\$</i> 1						
		•										
Part No):	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _				
	R	esolution:	Disposition	າ:	_ QA: N/C	Closed:		Date: _				
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NC	R)						
DATE	STEP	Description of NC			on B	Verifi	cation	Approval	Approval			
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector			
			·									
								Į.				
	 .											
	 · 											